




- DE** Montageanleitung
FR Instructions de montage
EN Assembly instructions



Picta 110
13022000 / 13025000



Picta 100
13021000











Picta
13032000




EN 1717 | EN 806 | DIN 1988


	P max. 1 MPa (10 bar)	0,1 - 0,5 MPa (1 - 5 bar)	
	T max. 60 °C	< 50 °C	
	V	1,5 GPM 13021000 / 13022000 / 13025000 0,1 MPa (1 bar) ≈ 3 l/min 0,3 MPa (3 bar) ≈ 5 l/min 2,2 GPM 13032000 0,1 MPa (1 bar) ≈ 4,5 l/min 0,3 MPa (3 bar) ≈ 7,5 l/min	










www.hansgrohe.com/search



* www.hansgrohe.com/warranty



hansgrohe

Hansgrohe · Auestraße 5 · 9 · D-77761 Schiltach · Telefon +49 (0) 78 36/51-1282 · Telefax +49 (0) 7836/511440
E-Mail: info@hansgrohe.com · Internet: www.hansgrohe.com

06/2026
9_04767_04